

0011



State of Utah

Department of
Natural ResourcesMICHAEL R. STYLER
Executive DirectorDivision of
Oil, Gas & MiningJOHN R. BAZA
Division DirectorJON M. HUNTSMAN, JR.
GovernorGARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:

Company	Mark Reynolds	Resident Agent
Company	Charles Reynolds	Resident Agent
OGM	Pete Hess	Environmental Scientist III

Inspection Report

Permit Number:	C0150025
Inspection Type:	COMPLETE
Inspection Date:	Thursday, May 15, 2008
Start Date/Time:	5/15/2008 8:55:00 AM
End Date/Time:	5/15/2008 11:35:00 AM
Last Inspection:	Tuesday, April 15, 2008

Inspector: Pete Hess, Environmental Scientist IIIWeather: Overcast; some rain during inspection.InspectionID Report Number: 1641
 Accepted by: jhelfric
6/2/2008
Permittee: **CO-OP MINING CO**Operator: **CO-OP MINING CO**Site: **BEAR CANYON MINE**Address: **PO BOX 1245, HUNTINGTON UT 84528**County: **EMERY**Permit Type: **PERMANENT COAL PROGRAM**Permit Status: **ACTIVE**

Current Acreages

10,967.39	Total Permitted
40.46	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- ☒ Federal
☐ State
☐ County
☒ Fee
☐ Other

Types of Operations

- ☒ Underground
☐ Surface
☐ Loadout
☐ Processing
☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

A review of the uploaded fourth quarter 2007 surface and ground water monitoring data by DOGM personnel revealed that the Permittee had failed to monitor for the ammonia parameter at five groundwater monitoring points and six surface water monitoring points. Also, nine other parameters were missed at surface monitoring site MH-2. Violation N10020 was issued to the Permittee as a hinderance for failure to properly conduct surface and ground water monitoring in accordance with the approved mining and reclamation plan on May 14, 2008.

There were no other violations issued during today's complete inspection of the site.

Mr. Shawn Baker is a new employee at the Bear Canyon Mine; he is working in the Engineering Department helping Mr. Mark Reynolds.

Inspector's Signature:

Date

Thursday, May 15, 2008

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Permit Number: C0150025
Inspection Type: COMPLETE
Inspection Date: Thursday, May 15, 2008

Inspection Continuation Sheet

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The Permittee has received a UPDES permit renewal, effective on May 1, 2008.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Ponds A, B, C, and D and catch basins 1,2, and 3 were inspected on May 13 and 14, 2008 by Mr. Mark Reynolds, P.E., and Mr. Baker. There were no signs of instability or other hazards noted during that inspection. All impounding structures retain sediment storage capacity below the 60% cleanout elevation.

9. Protection of Fish, Wildlife and Related Environmental Issues

The Permittee has contracted to do the annual raptor survey on May 22, 2008.